

0	Quick Turn Items
Highlighted	Flying Responds
Silent	Silent Checklist

BEFORE START

Flashlights.....	OPERATIONAL
Oxygen Masks/Systems	CHECKED/NORMAL
0 Oxygen Qty	CHECKED
0 Circuit Breakers.....	CHECKED
0 Generators(except for GPU start)	GEN
Fuel Boost Pumps	NORM
Ignition	NORM
Anti-Ice/De-Ice Switches	OFF
Crossfeed	OFF
Gyro Slave Switches LH / RH.....	.AUTO
Control Lock.....	OFF
Stby Gyro.....	ON/VERIFY PWR/OFF
Seat Belt Sign	CHECKED/OFF
Anti Skid.....	OFF
0 Cabin Press / Rate Control	SET
Throttle/Engine Sync	CUTOFF/OFF
Flap Indicator/Selector.....	SET/MATCHED
Windshield Bleed Valves	CLOSED
Batt Switch-EMER	EMER BUS PWRED
Batt Switch-BATT	24V MIN.
Rotary Test	CHECKED
0 Parking Brake.....	SET
Landing Gear	3 GREEN/NO RED
Cockpit Voice Recorder	TESTED
Engine Instruments.....	NO FLAGS
0 Electric Elev Trim	TRIM DISC CHECKED
0 N1 / Airspeed Bugs	SET
0 GPS.....	PROGRAMMED
0 Fuel Qty.....	SUFFICIENT/BALANCED

Battery Off until passengers are boarded**START**

Cell Phones	OFF
Chocks.....	REMOVED
Beacon/Nav Lts	ON
Stby Gyro.....	ON
INVerter Pwr & Master Avionics	OFF
Air Conditioning	OFF
Cabin Door / Keys	LIGHT OUT / ONBOARD
Start Check	COMPLETE

BEFORE TAXI

GPU	DISCONNECTED
Generator Switches.....	GEN
Volts/Amps	CHECKED
AC Power & Master Avionics	ON
Pass Advisory Light.....	PASS/SAFETY
Cabin Press and Temp Controls	SET/AUTO
Gyro Pressure	CHECKED
Overhead Fan	AS REQ
Coffee/Freon AC	AS REQ
Circuit Breakers.....	CHECKED RT/ CHECKED LT
Belts and Harnesses	ON RT/ ON LT
Before Taxi Check.....	COMPLETE

TAXI Check

Departure Runway	BUGGED/VERIFIED
Transponder	AS REQ
Brakes and Steering.....	CHECK RT/ CHECK LT
Flight Controls	TOPS CHKED/ BOTTOMS CHKD
GPS	PROGRAMMED
Inverters	CHECKED
AP & Flight Director.....	CHECKED/HDG-ALT SEL.
Anti-Ice/De-Ice	CHECK AND AS REQ
Thrust Reversers.....	CHECKED
Flight Instruments.....	CHECKED
Altimeter/Alt. Selector.....	SET
Radios/Avionics.....	SET
Fuel Qty/Balance.....	CHECKED
Press Source Selector	CHECKED LH/RH/NORM
Speedbrakes	CHECKED / RETRACTED
Standby Gyro	UNCAGED
Flaps.....	SET °/SET °
Trims	SET 3 TIMES
Takeoff Data / Bugs	REVIEW
Crew Briefing.....	COMPLETE
Taxi Check	COMPLETE

BEFORE TAKEOFF

Ignitions	ON
Anti-Ice/De-Ice	AS REQ
Pitot/Static Heat	ON
Lights	ON
Transponder/TCASON
Engine Instruments	CHECKED
Anti Skid	ON
Annunciator Panel.....	CHECKED
Departure Runway	BUGS ALIGNED/ VERIFIED
Before Takeoff Check	COMPLETE

CLIMB (silent)

Landing Gear & Lights UP AND OFF
 Yaw Damp ON
 Flaps UP
 Engine Sync ON
 Ignitions NORMAL
 Climb Power SET
 Anti-Ice/De-Ice AS REQ
 Pressurization CHECKED
 Pax Advisory Lights AS REQ
 Climb check COMPLETE

TRANSITION (climb)

Altimeters 29.92/29.92-XCHECKED
 Recog Lts OFF
 Oxygen CHECK RT/CHECK LT
 Pressurization CHECK
 Air Conditioning FAN OR OFF
 Transition Check COMPLETE

DESCENT

Defog Fan HI
 Foot Warmers CLOSED RT/CLOSED LT
 Airflow Distribution COCKPIT
 Pressurization SET
 Windshield Bleed Air/Manual Valves LO/MAX
 Anti-Ice/De-Ice AS REQ
 Fuel BALANCED/CROSSFEED OFF
 Descent Check COMPLETE

APPROACH

Altimeters SET/CROSSCHECKED
 Belts and Harnesses ON RT/ON LT
 Passenger Seats UPRIGHT/OUTBOARD
 Cabin and Emergency Exits CLEAR
 Recog Lts ON
 Landing Data SET / POSTED
 Anti Skid ON
 Pressurization CHECKED
 Avionics/Flight Instruments SET
 Approach Briefing COMPLETE
 Passenger Advisory Lights PASS/SAFETY
 GPS selector TO NAV
 Approach Check COMPLETE

BEFORE LANDING

Land Gear DOWN-3 GREEN-NO RED/VERIFIED
 Ignitions ON
 Engine Sync OFF
 Pressurization CHECK ZERO DIFFERENTIAL
 Landing Lights ON
 Flaps LANDING
 Annunciator Panel CLEAR
 Speed Brakes (Prior to 50 ft AGL) RETRACTED
 Autopilot / Yaw Damp OFF
 Before Landing Check COMPLETE

AFTER LANDING (silent)

Anti Skid OFF
 Pitot Heat/Anti-Ice/De-Ice OFF
 Ignitions NORMAL
 Ext. Lights AS REQ
 Stby Gyro OFF/CAGED
 Transponder AS REQ
 Radar STBY
 Flaps UP
 Speedbrakes RETRACTED
 Trims RESET
 After Landing Check COMPLETE

SHUTDOWN Check

Parking Brake AS REQ
 Transponder STBY
 Avionics & Inverters OFF
 Overhead/Defog Fans OFF
 Freon A/C OFF
 Throttles CUTOFF
 Exterior Lights OFF
 Pax Advisory Lights OFF
 BATT Switch OFF
 Clock ZEROED
 Shutdown Check COMPLETE

 V_{REF} – KIAS

Flap	WEIGHT						
	14,1	13,5	12,7	12,0	11,5	10,5	9,5
V_{REF} Full	114	112	108	106	104	99	95
V_{APP} -15	122	119	115	113	111	106	102